



NOTE:

- (1) Fix angle and seal to sides of box. At sides and base, claddings shall overlap by 10mm minimum. Continuously seal cladding against angle.
- (2) Suitable for other similar penetrations